

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.


As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.

TORQUE TUBE. THE INTERNATIONAL NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB. 1937 1938

VOLUME XVII . NUMBER 6 . JULY/AUGUST 1999



The Childen (#651) EDITOR



Dear Members, another year has passed and it's now time to renew your subscription. Check the envelope label your *Torque Tube* came in. If it reads: *Expires September 1999*, then it's time to renew! There is also an addressed renewal envelope included with your magazine. Dues are \$34 for US, \$35 for Canada and Mexico and \$40 for all others. Overseas surface mail is \$35/year. To renew for more than one year, submit the above amount times the number of renewal years. *Thank You.*

We ended our 1998-1999 publishing year with over 625 paying members, an all time high. Our current membership owns 652 1937 and 1938 Buicks. 310 '37's and 342 '38's!

Recently spoke with a professional car mover. He said if you transport a car on a flat bed truck, be sure **not**

to put a car cover on it as the flapping cover will rub off some of the car's paint. Then today I spoke with a collector who said he transported a car on a flat bed truck with a cover on it. And yes, it did rub a lot of the paint off. He learned his lesson the hard way!

Our first photo shows some of the American cars used in the filming of Saving Private Ryan in Hatfield, England. That's Derek and Kate Hodgett's (#690-Nottingham, England) 1937 Limited Sedan in the middle.

When sales slumped in the late 1950's, Buick changed the names of its entire product line, summarily replacing Roadmaster, Super, Century

> and Special and introduced three new lines - LeSabre, Invicta and Electra.

The division's emblem, introduced on all 1937 models, was based on the Buick family's Scottish coat of arms.

It was re-configured in 1959 to became three overlapping shields to commemorate the three new models. And that's how the famous Buick tri-shield logo was born!






TORQUE TUBE



This Buick Owner Service Policy was found by John Baine (#1070) in Canada. It was with some parts he purchased. It's for a 1938 Roadmaster Phaeton Model 80C. The car was pur-



chased by Mary Durvee from Glidden Buick Corporation at 3261 Broadway, New York City, NY. The Engine number was 8-3453527 with the first "8" indicating an 80 Series or Roadmaster car. The Serial (frame) number was 1-3278640 indicating a Flint assembled car (as were all 1938 open Buicks). If the frame number began with a "2", it would be a South

Gate (Los Angeles) assembled car. A "3" would be a Linden, NJ assembled car. We have five members who own Fisher bodied 38-80C's. Perhaps one of them owns this car? The next photo shows Art Benton's (#995-San Jose, CA) mother and stepfather on a Canadian vacation in 1937. The car was a new 1937 Century Slant Back Sedan Model 67. After two years, it was traded in on a 1939 Century. Then in 1940 on a new Nash, mainly because the Nash's heater was superior to the Buick's! Art writes that



they would go to his mother's old uncle's house in Pennsylvania in the '37 Century. He was always glad to see them and the Buick. His house had no electricity, so when they got there, he would listen to the baseball games on the Buick's radio.

Von Hardesty (#964 in Virginia)

owns this maroon 1937 Century Convertible Coupe Model 66C (top of page 3). He has just had it repainted in the original Sandringham (dark) Maroon. Von recently purchase a companion for this car

It's a beautifully restored maroon 1940 Ford Convertible Coupe. Von says, "The Ford is a real beauty, the most complete and detailed car I've

= TORQUE TUBE=

You can now find your '37-'38 Buick Club on the World Wide Web: http://www.classicar.com/clubs/buick/buick.htm

The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:


The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA

You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Editor:......Harry Logan, #651
Art Director:......Dug Waggoner, #10

Printer Liaison: Bill Olson, #427
Printer: Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE



ever owned...it's just pristine."

The previous owner spent 9 years restoring

it and went to great expense of replicating the old style top. The rear window has original style snaps and belts, with Ford script on the windows. The previous owner even found an original 85 hp V-8 engine

block, still in the crate! It's a strong driver and quite in the 0 to 60 mph range.

I've seen this heater hose bracket bent and mounted to either the spark plug cover or engine breather bolts. The factory correct way was attaching it to the center valve cover bolt. Late 1938's did not have a center bolt, so the bracket must be mounted differently or left off.

Spoke with a 1937 Roadmaster owner. He said he switched his tires from 7.00 x 16 used on 37/38 Roadmaster's to 7.50 x 16 tires used on the 37/38 Limited. He said it effectively changes the rear end ratio from 4.22 to around 4.10 and the engine

turns over about 400 rpm slower than before. But if you have sidemounts, you can't put the

larger Limited tire in the fenderwell.

If you want to run 12 volt accessories (like a radio or CB) on a 6 volt system, you will need to get Voltage Inverter. It converts 6v dc to 12 v dc. Be sure the 12 volt accessory you

want to power does not draw more current than the Inverter can provide. Radio Shack, I am told,

no longer sells them. The only place I know of that sells them is Antique Automobile Radio in Florida. Phone 1-800-933-4926. Ask for their catalog, or check with your local CB or HAM radio supplier.

Bill Denney (#863) in Australia is restoring a 1938 Century Convertible Sedan Model 60C. 37/38 open cars have a channel for a tacking strip in the back where the cloth top meets the body. The tacking strip helps hold the top in place. Bill could not find anyone in Australia that sells this 5/8" wide





could not find anyone in Australia that sells this ⁵/ 8" wide strip. So he used a section of a fan belt. He says it fits like it was made for it and dense enough for the tacks to hold.

During a visit to Central Otago New Zealand,

Bruce Webster, friend of the Torque Tube's art director, came upon an interesting find. This

1937 Buick Special Sedan (top photo) is in the city of Dunedin, NZ Settler's Museum. It was purchased new, from a Buick franchise "from way back" in Dunedin, by a local farmer who used it for 21 years. He sold

both his car and farm to a couple who drove it until 1965 when it was retired to the farms hay barn. A full professional restoration to its origi-

nal splendor and color was completed in 1987. The owners at the time have since passed away and the car now belongs to their daughter who has loaned it to the museum for display.

This photo of a light colored 1938 Buick coupe, with polo mallets was taken in Florida by famed photographer **Russell Lee**, circa 1939. It's from the

Library of Congress web site (www.loc.gov). Thanks to **Von Hardesty** (#964 in Virginia) for sending in this interesting photo.

This 1938 Motor Age Magazine cartoon reflects the pricing of gasoline (petrol) and the



chauvinistic attitueds of the times.

Member Don Johnson (#960) in Flint, MI owns a restored 37-66C and 37-80C. He also owns a 1938 Century Sport Coupe that was purchased new by his cousin. Don

has lived all his life in Flint and has seen many changes. His great-grandfather was James H.


Whiting, the man who was responsible for bringing Buick from Detroit to Flint in 1903. At that time, Mr. Whiting was the owner of the Flint Wagon Works. He foresaw the demise of horse drawn vehicles and wanted to get


into the fledgling automobile business, so he purchased the Buick Motor Company. At that time, David Dunbar Buick was running the company.

but he was not a good businessman. So in 1904, when Mr. Whiting saw his investment failing, he hired William Durant to take over running the company. In 1908 Durant formed the General Motors Company with Buick as the cornerstone of the corporation. And the rest, as they say, is history!

In among the many

letters I received a nice one from member Gene McCoy (#573) in New York who wrote: "When it comes to getting the best service and used parts for our cars, you need look no further than our own Dave Tacheny (#997). He is effi-





"Oh boy, I'll take five of them."

cient and more importantly, honest."


Notice, in the photo at the top of page 5, the '35 Ford and '37 Buick Convertible Coupe with sidemounts, fog lights and the top down behind the hot rod. One wonders what's going through the minds of the trio in the Hot Rod. With both hands on the dashboard, the girl seems to be thinking that with no seat belts or air bag her best move would be to pray for a miracle in the event of a crash. The guys are wishing this wasn't their sister. Thanks to David Boos (#569) in Southern California for sharing this interesting photo.

This ad for a Redfern Saloon-Tourer (convertible sedan) appeared

in March, '39 in the London Times. The McLaughlin-Buick was bodied by Maltby's Ltd. of Folkestone, England. While this is a 1938 car, it's very similar to *Vic Lane's* (#1040-Wales, U.K.) 1937 Maltby bodied Buick that appeared in the April/May issue. Thanks to *Bob Ward* (#114) in Ontario, Canada for sharing this ad.



Again, thanks for your continued support and I want to share with you a surprise from BCA. At this year's National Meet, in Columbus, Ohio our *Torque Tube* was given the 1999 Annual Newsletter Award for excellence.



(Cover Cars)

This Samarra Beige1937 Century Convertible Sedan Model 60C belongs to **Jack Shepherd** (#138) in British Columbia, Canada. Jack purchased the car from **Greg Field** (BCA #1) in Los Angles and restored it to the beautiful condition it's now in. Jack drove it to the last 1937-1938 Buick Club Western Meet at Mount Hood, Oregon in 1997.



discovered with delight your site on Internet and I realized that my passion is shared by other people. I like antique cars, especially American ones. But 1938 Buick has unique place in my heart.

I am the happy owner of a 1938 Buick Special Sedan Model 41. The original owner - my uncle - purchased it new. Then it became the object of his veneration for almost 50 years. The deep respect I felt for my uncle, and the passion for antique cars made me cherish his car the same way from the moment I inherited it. All this time since the Buick became a family member many difficulties appeared.

An important problem for my uncle was to keep her away from Communist persecution in the '50's when she was considered a symbol of the American Imperialism.

With another kind of problems I had to fight after the fall of Communism. The economical crisis and our authorities lack of interests of preserving such a valuable object like a 1938 Buick made my efforts to keep her in good shape a nightmare.

The specialists my uncle knew passed away and now there is nobody who could repair a car older that 20 years. My principle problem is the carburetor. I desperately looked for a




similar model in my country hoping that I could solve my problems even by exchanging spare parts. The conclusion was I am the only owner of a Buick made before the War. I think you will understand why I felt my life changing the moment I found out about the existence of your Club.

Do you think you could help

me? Hoping for good news from you I wish you to enjoy your cars as long as possible.

Yours sincerely,

Ivan Nicolaie



If you would like to contact Ivan Nicolaie, here's his address:

Sos Pantelimon, 336, Bl. 5A, Sc. A, Et. 8, Ap. 33, Sector 2 Bucharest, Romania

Tel: 004016281470

E-mail: lenciu@securities.ro

AN UPDATE ON BUICKS

ED: Since the article "Canadian Buicks-A McLaughlin Buick Primer" appeared in the July/August 1998 Torque Tube, I have received letters from McLaughlin-Buick owner John Baine (#1090) with additional information on these cars.

Canadian cars carried the name McLaughlin

this case the 1,597th 1937 McLaughlin built dur-

ing the model year.

until 1942. After that they were simply "Buick." According to GM of Canada, a total of 191 48-19 Roadmaster five passenger sedans were produced in Oshawa, Ontario in 1938. A further 58 were exported. These figures were not broken down into body type. I'm not sure if any convertibles were produced in Canada. It appears GM of Canada did not preserve all of the records for that time period.

Here is what a 1938 Canadian Buick hubcap looks like. They are on my 1938 Roadmaster and are

very hard to find, especially in good condition!

This is a '37 Canadian Data Plate. The Serial Number is 744191597. The first digit is the model

year, 1937. The next four digits 4419 are the Fisher Body style number for the car, i.e. 4419 is a Special 4-door trunk back sedan. (4=Buick, 4= 40 series Special, 19= four door trunk back sedan. The digits 1,597 represent the vehicle serial number in sequence, in



At the bottom of US data plates it's marked BODY BY FISHER but the Canadian ones are not. This US data plate is for a Wellington (dark) Gray1937 Roadmaster Trunk Back Sedan Model 81 with a Mahogany colored dashboard.


The Fisher body plate is found on the lower right side of the cowl on the outside and is red. (ED: also the same location on US Fisher bodied Buicks except the color is black).

The '37 McLaughlin Buick horn button and


grille badge were also different than on US Fisher bodied cars. The engine color was Buick Green, but the valve and spark plug covers were painted

black. And not all Canadian cars had 6 bolt studs on the wheels. Specials did, but I'm not sure about the Century. Probably they did. I have never seen a Canadian Century.

The Roadmaster has 5 and are actually bolts that thread into the brake drum.







1937 US Data Plate



Fisher Body of Canada Plate



Grille Badge

or many, 1937 was a peaceful, happy year. Yet there were some deeply disturbing trends. The Japanese sank the US gunboat Panay, stationed on the Yangtze River near Nanking, China. Several American oil tankers were also sunk by Japanese gunfire that year. But Japan was a long way off, and we failed to recognize these

Adolf Hitler repudiated the Versailles Treaty of World War I, and released the Reichsbank from the payment of reparations, and prohibited Ger-

incidents as portents of worse news to come.

mans from receiving Nobel Prizes, substituting similar awards for which only citizens of the Third Reich were eligible. But again, we failed to recognize the significance of Der

Führer actions.

On the home front, there was labor trouble in

America's auto factories. To fight back against management, the United Auto Workers Union (UAW) used an unusually effective technique known as the "sit-down-strike." The largest strike occurred when 140,000 workers sat down on the job at seventeen General Mo-

tors plants, bringing one of the country's largest industries to a standstill (or in this case a site-still). While GM was having labor





trouble, Ford produced its 25 millionth car.

Below, UAW members are staging a sit-down at a General Motors plant in Flint, MI. The headline of "The Flint Auto Worker" newspaper one of the workers is reading says STRIKE SPREADS. (Thanks to Charles Jekofsky (#524) in Washington, DC for sharing this photo).

Most Americans were much more interested in the spectacular coronation of King George VI, the father of the present Queen. Or in the new heavyweight boxing champion, Joe Louis. Or in the 46 home runs scored by Joe DiMaggio for the New York Yankees. (This photo of Joe appeared on the cover of the September, 1941

Motor Age magazine).

Lakehurst, New Jersey,

Or in the opening of the spectacular Golden Gate Bridge. The ladies were enthusiastic about the development of Nylon hosiery. And all were stunned by the tragic loss of the Hindenburg, the world's largest dirigible, which exploded and burst into flames as it approached the mooring mast at the

transplane
plane
i n g
to New

Howard Hughes established a new continental airspeed record, flyfrom Los Angeles York in just seven

hours, 28 minutes. But Amelia Earhart, America's premier aviatrix, was less for-

tunate. In an attempted round-the-world flight, she and her navigator Fred Noonan, were lost

somewhere in the New Guinea. No plane has ever and exactly what them is still a speculation.



vicinity of trace of their been found, happened to matter of

Radio was big in those days. Popular programs included Myrt and Marge, The Goldbergs, and a somewhat hokey program Voice of Experience. Jack Benny and Fred Allen carried on their friendly feud, and Candice Bergen's father Edgar, a newcomer to the air waves, was making it big with the help of his ventriloquist's dummy, Charlie McCarthy.



spenser Tracs

New on the literary front were Ernest Hemingway's To Have and Have Not, Kenneth Robert's

Northwest Passage, and A. J. Cronin's The Citadel, that, during 1938, would

along with one that, during 1938, would take the Pulitzer Prize: J. P. Marquand's The Late George Apley.

In Hollywood, meanwhile, the Oscar for Best Picture went to The Life of Emil Zola, starring Paul Muni.

Academy Awards also went to Spencer Tracy, for his

leading role in Captains Courageous, and to Luise Rainer for The Good Earth. Another favorite was A Star is Born, starring Janet Gaynor and Frederic March. Thirty-six year old

Clark Gable was crowned "The King of Hollywood" in a poll of readers of Ed Sullivan's newspaper column.

Popular songs included A Foggy Day and

Clark Gable



Nice Work If You Can Get It, by George and Ira Gershwin; Where or When and The Lady Is A Tramp by Richard Rodgers and Lorenz Hart; Sweet Leilani by Harry Owens; (a big one for Bing Crosby, and the year's Academy Awardwinning song); Too Marvelous for Words, by Richard Whiting and Johnny Mercer; and Rosalie by Coel Porter. Tuneful, sentimental songs they were, many

of them still popular today.

The dance craze of the time was a sort of modified square dance called the Big Apple. But the real sensation for the youth was swing music. Swing music in general and the Benny Goodman band in particular. Goodman was at the top of his form in 1937, with a band that



James and Ziggy Elman on trumpets, Lionel Hampton on vibes, Gene Krupa on drums and of course Goodman himself on clarinet.

Bill Cosby, US

comedian; Saddam Hussein, Iraqi president; Dustin Hoffman, US actor and Jack Nicholson, US actor were all born in 1937. Jean Harlow, US actress; John D. Rockefeller, US industrialist; George Gershwin, US composer all died in 1937.



ohn D. Rockerfuller

From a'70 Cutlass to a'37 Buick

By Danny Vincens (#1359)-Chalmette, LA

As far back as I can remember I have always been a car enthusiast. Several year ago I purchased a 1970 Cutlass SX Convertible and restored it to original condition. I then assisted my friend *Frank Marengo* (#918) restore his 1937 Buick Coupe. That's when I fell in love. Every now and then Frank would give me the privilege of driving his coupe and I realized I enjoyed driving it better than the Cutlass.

One day Frank received correspondence from Dave Tacheny (#997) that he had recently acquired

a '37 Buick Special Model 41 and would send him a photo if he was interested. Unknown to me, the luckiest day of my life was when Frank said, "yes". I happened to be at Frank's house when the photo arrived. After one look, I

started to ask a million questions and Frank caught on right away. Together we called Dave and he agreed to send more photos. After the photos arrived, I decided the Cutlass was For Sale and a road trip was planned. It didn't take long as the

Cutlass sold in three days.

I borrowed a friends Chevrolet Suburban and reserved a U-haul trailer in Minneapolis, Minnesota. Immediately after lunch on a Sunday afternoon, Frank and I set off on our journey from Chalmette, LA (just outside New Orleans). Taking four hour driving shifts, with only stops for gas and a quick dinner near St. Louis, MO., we arrived at Dave's home in Champlin, MN at 10:30 am on Monday.

Dave greeted us and then backed the Buick out of the garage and the inspection began. Everything was there, not a part was missing and it only had 65,000 original miles. We cranked it up and it purred with only an occasional miss, due to lack of maintenance. We drove around the neighborhood and the brakes pulled to the left, but the drivetrain performed flawlessly. When Dave acquired the Buick it had seat covers. Dave removed the

front seat covers and found the interior was perfect. Included in the deal was all the original paperwork.

The original owner was E. B. Fay of St. Louis, MO who stored the car at his summer home on Washington Island, WI. Since it was only used during the summers, the body is rust free.

A deal was struck and the Buick was mine. We then had time to look through Dave's garage for some parts Frank needed. After lunch, we took a ride to Dave's barn to look at several 1937 and

1938's Dave was parting out. We picked up the trailer and loaded up my prize and left Dave's at 3:30 PM Monday.

We thought about stopping for the night but the adrenaline was flowing and we wanted to get this

prize home. Every stop we made on the way back took an extra fifteen minutes as the Buick would always draw a crowd. The trip home was nearly uneventful with only one wrong turn in Rockford, IL which cost us \$4.00 in tolls to nowhere.

As we neared Louisiana, we called our wives and had them meet us at my house so Frank and I could sneak to his house to give the Buick a quick wash as we drove through a rain storm on the way home. We drove the one mile to my house and arrived with horns blaring at 5:30 PM Tuesday. The 53 hour road trip now seems like a blur, but it was the best trip I ever made!

The entire neighborhood turned out to greet "Daisy" (a name my wife and daughter gave the Buick). The consensus of the neighborhood is 1 had made the right decision in selling the Cutlass.

After rebuilding the carburetor, fuel pump, brake systems and a tune-up, Daisy is running like she just came off the assembly line. Only minor dents and scratches in the paint is all that is needed to put the Buick in top condition. But that's another story. (ED: Thanks to Frank Marengo and Dave Tacheny for reminding us what this Club is all about).



My Father's Car

By John Lalagos (#1309)-Bartlett, Illinois



his 1938 Century 2-Door Trunk
Back Sedan was purchased new by
my father. It has been driven by
all our family members including
myself and my 2 brothers as our first car when
we were teenagers. The last one to drive it rebuilt the engine, drove it for about 50 miles and

put it in a garage for 15 years. I removed it, put in some gas and pull started it. I then drove it 30 miles and put it in my barn. It sat for the next 21 years until last year when I started a ground-up restoration.

In September of 1997 I read


about the 1937-1938 Buick Club in Old Cars Weekly. I joined and received my first issue of the Torque Tube. It became the inspiration to restore my father's car.

The car was restored in four different shops

beginning January, 1998. It was finished six months later. The paint is Corot Beige, it originally was black. I must say that without the help of *Dave Tacheny* (#997), this project would not have been possible. He is courteous, most fair in all his prices and a total wealth of knowledge and information. If Dave can't advise you or find

what you need, it doesn't exist. Bob's Automoblia was also most helpful with my restoration.

I also own a '36 Ford and a '66 T-Bird convertible. Since this Buick was finished, I have not driven my other cars. It's a dream





SOME INTERESTING 1937-1938 DATA PLATES


By Harry Logan (#651)-Los Altos, CA




This data plate is on a 38 Century Sedan Model 61. Note the "6" in the upper right corner, indicating the car came with sidemounts. Buick called these factory sidemounted cars "6 wheel jobs."



This data plate is on Bob Lawrence's (#653) 1937 Special 4-door sedan Model 41. It is the only data plate 1 have ever seen where the date is filled in. It is stamped 11-24-36, indicating an early production '37 Buick. The paint was #501 Chancellor (dark) blue with #301 upholstery (tan mohair fabric).



This data plate is on a 1938 Buick Special Convertible Coupe Model 46C. The unusual thing about it is the "G" stamped in the lower right hand corner. I have now seen this "G" on three '38 Special Convertible Coupes .




1937 80 and 90 series cars had the first letter of the dashboard color stamped in the lower right corner. "B" for black, "M" for mahogany and "G" for gray. Perhaps this carried over to 1938 or it might possibly mean the color of the convertible top. 1937 and 1938 top colors were tan, blue-gray and black. Does anyone have any information on what the "G" might mean?




Technical CONVERTIBLE RUBBER PADS


By Harry Logan (#651)-Los Altos, CA




This factory photo of a 1938 Buick Convertible Coupe's shelf shows a rubber pad. It was screwed to the rear shelf with one pad on each side waiting for the two chrome feet to come down when the top is lowered.



POSITION OF CHROME FOOT WHERE IT MEETS THE RUBBER PAD



Two chrome feet, one on each side of the top bow, rested on the rubber pads when the top was down. I believe convertible sedans also used these metal feet and rubber pads.



You can order a pair of these 1 3/8" long by 9/32" tall pads from either *Lynne Steele* in North Carolina (1-800-544-8665) or *Bob's Automoblia* (#805). These were in stock when I ordered them from Bob's in June. The Steele part number is 70-0280-88. The cost is around \$34/pair. You might also be able to cut these out of a rubber strip. They're held in place by two wood screws.

Without these pads, the top feet may not rest on the shelf. One convertible owner reports that without these pads, he had to fold the top between the feet and shelf so that they had something to rest on.



Technical GM DRIVING AND FOG

By Harry Logan (#651)-Los Altos, CA

The factory fog lamps for our 37/38 Buicks a raised comb on top such as in the photo.

were these GM Guide brand lamps. These are the actual Guide Fog Lamps (A) ordered with this car in 1938. The original bill of sale shows they cost \$11.00 a pair installed.


You could order either (B) Guide fog lamps (amber lenses) or

Driving lights (clear lenses). The purpose of the driving lights was to "throw a concentrated controlled beam down the highway, picking out



In a side-byside comparison to the Lorraine's. the Guide's fog lamps and driving lights have a plain top (D). I have a Guide fog lamp Instruction sheet. It reads: "The installation of two lamps is strongly recommended. If only one lamp is used, mount it on

the left side of the bumper. In heavy fog, both fog lamps should be turned on and the headlamps switched off for best possible re-



turns, signs or possible obstructions, beyond the sults." I was surprised GM recommended

range of the headlamps."

Most 37/38 Buicks I've seen have aftermarket lamps such as this (C) Lorraine, made by Appleton Electric Co. of thicago, IL. There were many other brands, some owner's prefer lamps with





switching the headlights off when the fog lamps were on. The Guide instructions state that both California and Pennsylvania have a law requiring the headlights to be turned off when using the fog lamps!

(Continued from page 18)

I rarely drive my '38 at night but when I do I use both the fog and headlamps for better visibility. I also use halogen headlight bulbs

which put out more light than the original tungsten bulbs.

This wiring diagram (E) is from the printed Instructions for Installing GM Fog Lamps. Most 37-38 Buicks today have a new wiring harness. These usually come with the fog lamp wires, so

you just need to run the lamp wire to a switch, usually mounted on the curved lip at the bottom of the dashboard, then through a fuse to a

OF CAR

6 volt source. To prevent accidentally leaving the fog lamps on, you might want to have them wired so the fog lamps go off when the ignition switch is

turned off. You can do this by connecting the lamps to the positive gas gauge terminal.

TO AIM THE FOG LAMPS

Illustration (F) shows the pattern of a properly

aimed fog lamp:

1. Place car on level place 25 feet (7.6 meters) away from garage door or clear wall.

2. Measure distance from floor to center of Fog Lamps. Draw a horizontal line on the door or wall at Fog Lamp center just determined.

3. Then draw a horizontal line on wall 4 inches (10 cm) below the horizontal line representing the Fog Lamp center.

TAIL LAMP

TERMINAL

OF LIGHT

SWITCH BLOCK

4. Spot vertical center of car on door or wall by sighting through rear window in line with the hood ornament.

5. Turn on Fog Lamps only, leave off head-lights, cover one lamp, then set head of the lampyour adjusting so that top of beam is at the

horizontal line spotted in step 3 and so that center of this beam is same distance from vertical line spotted in step 4 as the vertical cen-


ter of lamp head is from vertical center of car. Then lock lamp in that position. Repeat this process with the other lamp.

Thanks to long time member Joe

Giordano (#333) in Missouri for sharing this information. Joe says these Guide lamps were used on '37 - '39 Buicks, '37 - '38 Chevrolet and Oldsmobile. He believes they were also

used on '37 - '38 Cadillac and Pontiac.

This (G) is a 1940 Guide Driving lamp. Joe says that the shape of the lamp changed in 1940 because of the difference in the shape of the front fenders.




CONNECT WIRES HERE FOR DUAL INSTALLATION RONT OF DASH

BATTERY

OF LIGHT

SWITCH BLOCK


CLAMP ON SWITCH





STUCK COLD IDLE CONTROL

By Harry Logan (#651)-Los Altos, CA



The purpose of the cold idle control is to prevent a cold engine from stalling by providing a fast idle speed during warm-up. The speed increases or decreases as the temperature of the manifold changes. Photo #1shows the position of the Cold Idle Control on the manifold. Photo #2 shows it up close.

The cold idle control consists of a a heat operated cam "K" mounted on the intake manifold. This cam serves as a stop for throttle stop screw "D".

The variable speed is obtained by using thermostat "A" which drives the cam "K". When the manifold is cold, thermostat "A" rotates cam "K" in a counter-clockwise direction, causing its thick

ACCELERATING PUBLIC ROD

ADJUSTING HOLES

WERTICAL & OF LEVER
LEFT HAND DRIVE
THROTTLE ROD HOLE

THROTTLE SHAFT

HIGHT HAND DRIVE
THROTTLE ROD HOLE
LUSE ON EXPORT CARS ONLY)

F-POINTER MUST
BE VERTICAL

PER HOUR


Cold Idle Control (Stramberg)


side to contact the idle stop screw "D" which speeds up the engine.

As the manifold warms up, the thermostat is heated and thus revolves the cam "K" in a clockwise direction until idle screw "D" is contacting cam "K" at its thinnest section, causing the carburetor throttle to close to a normal hot idle speed.

With the throttle screw not touching the cam, you should be able to pull the cam clockwise and it will

spring back when let go. My cam was stuck and would not move. I took it apart, drove out the brass bushing with the arrow pointer. Then I wire-brushed and cleaned the bushing and cam and now it works fine.





INTERMITTENT Technical IGNITION **SWITCH**




By Harry Logan (#651)-Los Altos, CA

The ignition switch A is mounted on the back of the steering column mounting bracket. It's held in place with two screws. Remove these screws and the wires attached to the two terminals and the switch will come out.


The switch consists of 3 pieces. B The metal case, bakelite cover and movable contacts.

When you move the ignition switch chrome handle, this pin C which



steel ball. It gives a positive feel when you flip the switch. If your switch moves from off to on without some resistance, this ball is probably missing.


My ignition switch was erratic. Sometime it would not turn on the ignition system. I thought I would remove and clean it. After taking it apart, I found that the bakelite cover had cracked D and was glued back to-



goes into the grooved bottom of the contact, causes it to pivot between the off and on positions. The chrome screw in the middle of the photo holds a small

gether. The result was that it had a slight curve. instead of being flat. I replaced the cracked bakelite cover and cleaned the switch contacts.

Now it works fine








By Harry Logan (#651)-Los Altos, CA

1937 BUICK VACUUM STARTER SWITCH

DELCO-REMY VACUUM STARTER SWITCH







SWITCH, Complete

*	1594	2.15	1934-35-36-40; 1937 if Marvel carbureter
*	1587	2.15	1934-35-50-60-90
	1601	2.15	1936-60-80-90
*	1607	2.15	1937 if Stromberg carburetor

(A) The Vacuum Starter Switch article in the January/February, 1999 issue warned that there were other vacuum switches available, like those shown above, that look like the 1937 switch. The correct switch is # 1607. This number is not stamped on the switch.


So to make sure you know what the correct switch looks like, here are some photos of an NOS '37 vacuum switch #1607 (B and C)

(D) shows the switch on the intake manifold. Hopefully, you won't end up with the wrong switch as I did. Anyone need a vacuum starter switch for a 1934-35-36 Pontiac?





(Continued from page 22)



New Members

Terry Knoepp (#1428) 10651 Caminto BanyonSan Diego, CA 92131

Ray Shanahan (#1429) 23 Briarwood Drive San Rafael, CA 94901 37-47

Joseph Boralsky (#1430) 28 Ash St. Stanhope, NJ 07874

James Peters (#1431) 6035 Chicwood Dr. Pulaski, VA 24301 37-46C

Eugene Mousel (#1432) 7556 East F St. Tacima, WA 98404

Vincent Pullara, Jr. (#1433) 1518 Ivy Hill Road Cockeysville, MD 21030 37-46C Avery Greene (#1434) 110 Scot Court Suisun, CA 94585

Doris Zicari (#1435) 99 Sagamore Dr. Rochester, NY 14617

Tom Barton (#1436) 960 N. San Antonio, Ste. 100 Los Altos, CA 94022

Louis Dalbec (#1437) 1351 Hall Street Manchester, NH 03104 38-81

Michael Keedy (#1438) P.O. Box 7451 Kalispell, MT 59904 37-66S

John McNerney (#1439) RR 1, Box 772 Venus, PA 16364 37-41 Donald Ischer (#1440) 299 Capital View Roseville, MN 55113

George Zappone Sr. (#1441) 173 Chimney Rd. Watertown, CT 06795 38-46C

Donald Short (#1442) 40 Bayshore Dr. Port Ludlow, WA 98365 37-40C

Randy Hosler (#1443) 6585 Dixie Highway Clarkston, MI 48346 38-66S

Walter Bruegger (#1444) 1289 Magnolia Ave. #1 San Carlos, CA 94070

Arnold Isaacs, Jr. (#1445) 20010 Colony Point Lane Cornelius, NC 28031

Parts FOR SALE

• 1937 & 1938 PARTS							
1936- possibly same as 1937 Century/Roadmaster. Two disassembled							
transmissions, large series							
						1938 Marvel Model CD 1B carburetor, complete with choke.	
						WasNOS but has been sitting for years	5225
1938 Century/Roadmaster/Limited AAV-2 with automatic choke\$190							
1937-40 SERIES SPECIAL PARTS							
Transmission, short tailshaft, open driveling floorshift. Same bolt pattern							
as Buick special							
Valve cover, clean, painted							
Bellhousing	\$25						
Thermostat housing, 2 piece							
Exhaust center manifold section, 40 series with heat riser							
Carburetor, AAV-1. Has been rebuilt, sitting in garage for several years							
• 1937-40/60 SPECIAL/CENTURY PARTS							
3.9 rear end, complete drum to drum with torque tube							
from '37 Century	\$375						
Bumper cores, front or rear. Need rechroming	\$30 each						
• 1937-ROADMASTER/CENTURY PARTS							
Engine, was running. No manifolds or carb	\$605						
Transmission	\$165						
NOS but has been sitting for years							
		Suspension, front end parts, used • 1937-ROADMASTER PARTS					
Rear end, complete. No drums	\$375						
Front seat frame, Good wood. Has adjuster, No cushion springs							
Front suspension parts							
	nquire						
All prices plus shipping Dave Powers (#894)							
27732 Paseo Barona							
San Juan Capistrano, CA 92675							
(949) 493-1199 evenings							
• 1937-CENTURY PARTS							
5-wheels and hub caps. Will trade for 1939 Century wheels.							
Paul Foley							
San Diego, CA							
(619) 660-6899							
• 1938 PARTS							
1938 Original Owners Manual with foldout lube chart, excellent							
condition, picture available by e-mail.	\$50						
Bill Neuendorff							
e-mail: bigbill@theriver.com (520) 458 8480 (Arizona)							

(Parts For Sale continued from page 24)	
1937 PARTS Automatic Choke for Sale. Fits all series	
James Moore Sr (#1121)	nquire
21 October Hill Rd.	
Hamden, CT 06518-1103	
(203) 281-0846	
E-mail: jimmoore@mail2.nai.net	
• 1938 PARTS & LITERATURE	
1938 Color Sales Catalog with black cover	
Accessory Bug Screen	
Rebuilt AF Series fuel pump for 40 Series cars	\$40
Marvel CD-1B rebuilt 40 Series carburetor	\$9
All prices plus shipping	
John Johnson (#697)	
276 N. Seymour Ave.	
Mundelein, IL 0060	
(847) 566-5005	
• 1938 PARTS	
Bumper, bumper badge and grille guard	\$300
Paul Blansky	
(724) 966-7358	
In Pennsylvania	
• <u>1938 PARTS</u>	
Left Front Fender, Fair condition	\$50
Right Front Fennder, Good condition	
Passenger Running Board, repairable core	\$50
Headlight Switch	\$15
• <u>1937 PARTS</u>	
Fender Marker Light	\$30
All prices plus shipping and handling	
Charles Wenger (#1278)	
(410) 877-7150, after 6 p.m. EST	
• 1937 & 1938 PARTS	
Parting 1937 & 1938 Buicks. The following is just a portion of the parts ava	ailable. Call with your needs.
• 1937 PARTS	
40/60 Series rear brake cables, good condition	\$40 pai
Coupe taillight, no stanchon or T bar	\$50
80/90 series trunk hinges	\$125
Master and deluxe heaters	\$75 each
Roadmaster rims	\$25 each
Roadmaster axles	\$100 pair
Roadmaster front suspension	call with needs
COURS N / Dr Sedan side stainless complete sets	
Coupe & 2 Dr. Sedan side stainless, complete sets	
Century brake & clutch pedal assembly	\$35
Century brake & clutch pedal assembly Century radiator	
Century brake & clutch pedal assembly Century radiator Special radiator	\$35
Century brake & clutch pedal assembly Century radiator	

(Parts For Sale continued from page 25)	
Small series throttle linkage	\$25
Big Series rocker assemblies	
Fender lights	
Trunk lights, complete	
Tail lights with lenses, all series	550 pair
Wiper transmissions	
Special manifold	
Throttle cable	
Special transmission	
Special splash pans	
Century hood	
Headlight switch	
Radio grilles	
Wiper motors	\$15
Trunk hold-up arms	\$20
Sun visors	\$15
Bumpers	\$30 each
Bumper arms	\$15 each
Steering wheel	
40 & 60 running board brackets	
Buick creast badge for hood trim strip	
Defroster vent	
Gas pedal	
Small and large series generators	
• 1938 PARTS	
emperature gauge, working with tube and bulb	\$50
Radio, working	
Jack, complete	
NOS amp and gas gauges	
DeLuxe Heaters	
40/60 series front bumper, not perfect	
40 & 60 sedan trunk lid, no rust	
Breather tubes	\$10 ageb
Trunk hold-up arms	
734Z starter with solenoid	220
Horn button	
Special hood lettering	
Defroster ducts	
Wiper transmissions	550 pair
Rear license plate stand, bracket & light for sedan	
Tail lights, complete	575 pair
Assist straps with screws	\$10 each
Throttle cable	\$20
Special radiator	
Battery tray	
Generator	\$50
Special manifold, complete	\$75
Special hood sides & tops	\$25 each
Grille, no cracks, minor pitting	5200
Century radiator	5100
Special coupe window moldings	S100

(Parts For Sale continued from page 26)	
Cigarette lighter	\$25
Century 3.9 rear end carrier and pinion	
Century motor, rebuilt, complete with AAV-2 and new clutch	\$2500 firm
NOS vacuum starter switch	
Rear muffler hanger, NOS	
Grille, some pitting	
• 1937 & 1938 PARTS	
Opera seat stands, 40/60 series	
Radio hanger bracket	
37/38 Century sidemount covers	
Big Series spark plug cover	
Special running boards, solid cores	\$200 pair
Headlight buckets	\$20 each
Large Series air cleaner	\$75
40-60 kingpin sets	\$30
Starter drives	
Large series fan belts, new	\$15
Map light switches	
Small series spark plug covers	
Rear fender splash aprons	
Big Series manifold ends	
16" beauty rings	
2 Door rear ash trays	
Headlight bezels	
그는 그	
Trunk hinges	
Front arm rests	
40 & 60 rear vent windows, need plating	
Rear view mirrors	
Special rear motor mounts	
Century rear motor mounts	
40 & 60 4 dr. sedan doors	
Front vent window frames & mechanisms	
Big Series fuel pump cores	
Keyed ignition switches	\$35
4-Post voltage regulator, used	\$25
15" Beauty rings	\$10 each
Headlight adjusting buckets	\$100 pair
Gas tank sending units	\$65
Dave Tacheny (#997)	
11949 Oregon Ave. N. • Champlin, MN 55316 (612) 427-3460	
(612) 427-3460	
• 1937 PARTS	
Left front fender, good shape	
Right front fender, fair shape	\$75
Grille, repro, fair to good	\$75
Special hood with stainless trim	\$45 per side
Special hood without stainless trim Dick Oellers (#1075)	\$35 per side
RR 4 Box 13820 • 100 Main Street • Winthrop, ME 04364 • e-mail: Rroellers@aol.com	(207) 377-6654

(Parts For Sale continued from page 27)

PARTS & ACCESSORIES

I am selling my 40+++ year car collection—56 restored cars—and 10,000 parts for 31 Marques—I have a 1936 and a 1937, and a1938 BUICK clock—\$100 shipped—I also have other BUICK literature, accessories—people can check my web page:

www.geocities.com/MotorCity/Street/6020

or send a SASE to:

ROY JUDD

2416 Hermosa Ave . Hermosa Beach, CA 90254

THANK YOU-I am anxious for my collection to go to car folks, not dealers

Parts WANTED

WANTED: 1937 PARTS

 1937 Radio - Here's your chance to unload a NON-working 1937 Radio. Must have the front assembly, would also like the casing, lower portion if possible. Do not need the inside assembly. Do not need a working or repairable radio. Basically looking for junk, but with non-working front assembly.

Will pay the cheapest price possible.

Bruce Lagomarsino (#1149) 2603 Hoffman Court El Dorado Hills, CA 95762 (916) 933-3025

WANTED: 1937 PARTS

 WANTED: Any front suspension and front brake parts for a 1937 series 90 Buick. I especially and desperately need all front suspension bushings and pins except king pins. I have an extra set of NOS king pins and bushings I would be willing to trade for the other bushings & pins.

Doc Scantlin (#1150) 2824 Ridge Road Huntingtown, MD 20639 FAX 301-855-9159

e-mail descantlin@docscantlin.com/swing

Phone: (301) 855-9102

WANTED: 1937 PARTS

1937 Special Gas Tank
Ed Kowalski (#1424)
1303 Gillespie Ave.
Portage, PA 15948
(814) 736-4897

WANTED: 1937 PARTS

 1937 Special Sidemount fenders, covers and hardware.

Jack McNerney (#1439)

RR 1, Box 772

Venus, PA 16364-9628

(814) 354-2459

WANTED: 1938 PARTS

- Choke control cable for Stromberg automatic choke
- Fuel line from pump to carburetor on a '38 Special with original factory bends.

Dick Oellers (#1075)

RR 4 Box 13820

100 Main Street

Winthrop, ME 04364

(207) 377-6654

e-mail: Rroellers@aol.com

WANTED:

1941 or 1942 Special Compound Carburetion Manifold, with or without carburetors and air cleaner.

James Rufener (#767)

19612 Salmonson River Road

Mora, MN 55051

WANTED: INFORMATION

 1937-1938 TOOLS: Doing research on Buick Hand Tools. Anyone with an NOS set in these cars please contact me to assist in this project concerning item identification. Thank you.

Charlie Halpin

405 Elliot Road

Elkins Park, PA 19027

E-mail: Wrenbody@aol.com

(215) 635-3256

Gars FOR SALE



FOR SALE: 1937 CENTURY

Two-Door Sedan Model 68 Dual sidemounts, working radio, rebuilt motor, wide white wall tires. Color of the car is bronze.

\$20,000. obo.

Irwin Mehlman (310) 399-6942

Venice, CA (Los Angeles area)

FOR SALE: 1937 CENTURY

Model 61 4 Door Trunk Back Sedan. Very original. Runs strong. New white wall tires. Nice original interior. Many extra parts, manuals in trunk. Original spare on rim with stripes. Photos available

\$8,000.

Steve Nathanson (#656) 69 Terrace Rd. Walnut Creek, CA 94596 (925) 947-6711

FOR SALE: 1938 SPECIAL

Trunk Back Sedan Model 41.
Burgundy, restored all original, ready to drive or show. Buick National winner. 70,000 miles \$13.500.

John Gillio (#1016) 15329 Ridgeland Oak Forest, IL 60452-1618 (708) 687-4303 Please call between 5-9 pm CST




FOR SALE: 1938 CENTURY

4 Door Trunk Back Sedan Model 61.Factory Sidemounts, original upholstery and woodgraining, nice blue paint (#519), Whitewall tires, AAV-2 carburetor, radio, heater, excellent original running boards, floor mat and jack. No trust. 1938 California plates. 70,000 miles San FRancisco car. Owner 20 years (second owner)

\$18,000.

Al Lovi (#994) 95 Brianne Circle

Windsor, CA 95492 (707) 837-1786



FOR SALE: 1938 CENTURY CONVT.

4-Door Convertible Model 60C

One of only 208 built. One of only 3 in the BCA roster. This car has been totally disassemabled and rebuilt from the ground up. It is about 75% done. It is driveable. It needs upholstery, some chrome, glass and a little rubber to finish it. I have about \$32,000 invested and about 500 hours of my own time in the car. Asking.....

| **\$28,500.** or best offer | David Bylsma (#117) | (410) 551-7236 (Maryland)

Back Jasues Still Available! THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 Volume X Numbers 1 through 9
 - 1992-1993 Volume XI Numbers 6 and 7
- 1993-1994 Volume XII Numbers 2, 4, and 6
- 1994-1995 Volume XIII Numbers 2, 4, and 6
- 1995-1996 Volume XIV Numbers 3 through 6
- 1996-1997 Volume XV Numbers 4 through 6
- . 1997-1998 Volume XVI Numbers 1 through 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

ONE OF A KIND CAR DISPLAY POSTERS:

Beautiful, Descriptive, Framed Collector Car DISPLAY POSTERS

for Car Shows are my specialty. These Hand Made Posters really add that "SPECIAL TOUCH" when displayed next to your car. Prices start at \$50.00 and up depending on Color, Size and Rendering of your car.

Al Lovi (#994) ART DESIGN STUDIO 95 Brianne Circle, Windsor, CA 95492 (707) 837-1786

CONVERTIBLE SUN VISORS

SUN VISORS Fits 1935-36-37-38-39

\$165.00 each

These are authentic visors. All parts are chrome plated.

WALLACE WAMSLEY

(619) 283-3063

4732 Bancroft Street #7, San Diego, California 92116

1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED. Complete Research Package \$50.00, \$60.00 if shipped outside the USA. Additional information available upon request, or send year, model, serial number, engine number, car photo (if available) and Fisher Body data plate rubbing.

1937 BUICK HIGH QUALIT

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



OMOTIVE RESEARCH SERVICES



P.O. Box 4057, Apopka, Florida 32704-4057 . Phone 407-880-0797 . e-mail: BUICKOHV@aol.com.

FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378.....\$195.



AUTOMOBILIA (805) 434-2963

1937-38 BUICK




DOOR WEATH	HERSEAL-SPONGE	=
	DW-378	
Clip-in	DW-80	\$5.25 ft.
Clips	WC-80	\$.75 ea.
DOOR BOTTO	M SEAL	
Clip Type	DW-369	\$2.25 ft



EXHAUST MANIFOLDS 1937-38 Series 60-80-90 ENDS \$185. CENTER \$189. VALVE BODY \$195.

Oub-111	
ClipsWC-80.	\$.75 ea
DOOR BOTTOM SEAL	
Clip Type DW-369	9\$2.25 ft
TRUNK SEAL-SEDANS. 1/	2* Wide:
Ser. 80-90TW-371	
Sedans, 3/4" Wide;	
Ser. 40-60TW-371	S\$37,50














HOOD REST PADS, 1937-38 6-8 Per Car.



CLUTCH and BRAKE PEDALS Series 40-60 BlackCB-343BK\$5.95 ea.








PEDAL FLOOR SEALS; All Models FS-375... \$12.50 pr.







1937 ONLY! ACCELERATOR PEDALS Series 40-60 Back. AP-37BK\$32.00 Brown...... AP-37BN\$35.50








SHIFT BOOT, 1937-38 Series 40 Only! Black \$ 9.25 Brown.....\$18.50 Series 80-90 Black ONLY.... \$ 8.50

DOOR SILLS: Trim To Fit



DOOR FERRULE INSTALATION TOOL. \$20. Refundable if Returned Within 30 Days. DF-TOOL\$29.



2-Door \$62/pr. 4Door \$93/set. GLOVE BOXES; \$27. ea. PARKING LIGHT LENS......\$18.00 ea

1938 TRUNK HANDLE/LIGHT MOUNTING SEAL......DH-381....\$8.95



CARB. KITS:CARTER......CK-360C .\$27.00 STROMBERG...... CK-37XS .\$27.50

MOTOR MOUNT, FRONT, All Models ROUND PADS..... SP-338... \$10. pr. MOUNT.......MM-347...\$51. pr



VISOR "VANITY" MIRROR. VM-379 \$27. ea.

TBK-343.\$27.00


TORQUE BALL SEAL KIT, All Models


LICENSE PLATE FRAMES. Chromed Brass LF-333P.....\$62. Pair



1937 HUB CAPS. All Ser HC-37 \$60. ea. WHEEL Beauty Rings. 15' or 16' \$99./Set of 4 1937 or 38 HOOD ORNAMENT......\$85.

TRUNK HINGES for 40-60. Chrome Plated \$150. pr.





SOME OTHER ITEMS WE STOCK; BEARINGS, DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING;10%, max.\$9. min. \$4. Prepaid, C.O.D. Add \$5.



BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write For Catalog)

BUICK...Upholstery and Top Kits 1927/1955

Since 1977 .. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits Seat Upholstery, Tops and related accessories as well as "era" fabric by the yard...

Inquire Toll Free

1-888-388-8726



HAMPTON

6 Chestnut St Tel 978-388-8047 ach Amesbury, MA



Restoration and repairs
that are correct
and authentic.
"I know your Buick."
Former Director of Long
Island, NY Chapter now has
fully equipped shop
in North Georgia.
Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945




J.B. Donaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505



Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927 TO 1953

WIRING HARNESSES

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
HAND CRAFTED WITH THE
FINEST MATERIALS
EACH SUPPLIED WITH:
LIMITED WARRANTY
INSTALLATION INSTRUCTIONS
SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION \$5



BOX 435 WAYNE, PA. 19087

